


8. Level 3 Repair

8-1. Block Diagram

Prato Block Diagram




8-2. PCB Diagrams


8-2-1. Top




8-2-2. Bottom




8-3-1. Power On





< Batt Connector >



HOLD & PWR ON

